



Government of Karnataka

DISTRICT SURVEILLANCE UNIT, MYSURU

NPC Hospital Compound, Nazarbad, Mysore-10 Phone No. 0821-2971847

Email ID :- **dsomysuru@gmail.com**

No. DSU/MYS/30/2025-26

Dated: 28.04.2025

Annexure C

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

It is to be certified that an inspection team headed By **Dr Nagaraja D G, District Surveillance officer, District Surveillance Unit, Mysuru.** inspected the BSS VIDYODAYA , #1498/22, ch-2/1, Rama Iyer Road, Krishnamurthypuram, Mysuru-570004, on the date **24.04.2025** , on the basis of water test report bearing no: UPHC/KMT/06/2025-26 Dated : 25.04.2025 from Urban Primary Health Centre, Krishnamurthypuram, Mysuru. Certified that the BSS VIDYODAYA, has safe drinking water facilities for the students and members of staff of the institution. School also maintains the hygienic sanitation condition in the school building and the campus as per norms prescribed by the Central/State/ U.T.Govt.

This Certificate is valid for a period of 28.04.2025 ONE YEAR 27.04.2026

Signature with Seal

Name:- Dr Nagaraja D G
Designation:- District Surveillance officer,
Address:- District Surveillance Unit, Mysuru

To

BSS VIDYODAYA
#1498/22, ch-2/1, Rama Iyer Road,
Krishnamurthypuram,
Mysuru-570004